


828 4th Street
Elk River, MN 55330
Phone (763) 441-1581
Fax (763) 441-1596



Page 2

ERMC / Acromix may recommend elevating the silo discharge. The screw auger will run more efficiently and with less initial cost